

SEACOMP

END OF LIFE NOTIFICATION (EOL)

<u>PCN NUMBER</u> EOL20002	<u>DATE</u> October 15, 2020
<u>CUSTOMER(S)</u> ALL CUSTOMERS	
<u>PROJECT(S) AFFECTED</u> DT028ATFT-PTS	
<u>EFFECTIVE DATE / OTHER REFERENCE</u> • March 31, 2021	

DETAILS

REASON FOR THE TERMINATION

Capacitive Touch Driver IC EOL.

LAST TIME BUY

March 31, 2021.

REPLACEMENT PRODUCT

Replacement suggestions: DT028BTFT-PTS2, DT028CTFT-PTS2.


EOL Capacitive Touch IC is FT5346. Replacement registers are backwards compatible with replacement IC FT5446.

If customer is replacing, SEACOMP recommends that customer verifies backward compatibility with existing product.

Thank you for your continued interest in SEACOMP products and services. For additional assistance or questions, please contact SEACOMP Customer Service at sales@seacomp.com or the sales contact you are working with.

Sincerely,

For and on behalf of SEACOMP



Cy Johnson

Director of Engineering

