

SEACOMP

PRODUCT CHANGE NOTIFICATION (PCN)

PCN NUMBER PCN20005	DATE October 30, 2020
CUSTOMER(S) ALL CUSTOMERS	
PROJECT(S) AFFECTED DT028BTFT-PTS1	
EFFECTIVE DATE / OTHER REFERENCE • October 30, 2020	

DESCRIPTION OF CHANGE(S)

REASON FOR THE CHANGE(S)

The original touch IC, FT5346, was EOL.

BEFORE CHANGE(S)

1. The touch IC was FT5346
2. Product P/N was DT028BTFT-PTS1

AFTER CHANGE(S)

1. The new touch IC is FT5446;
 2. The new product P/N is DT028BTFT-PTS2
- Replacement PCAP Driver IC: FT5446. Focaltech indicates backward compatibility with FT5346.
 - SEACOMP recommends that customer verifies backward compatibility with existing product

Thank you for your continued interest in SEACOMP products and services. For additional assistance or questions, please contact SEACOMP Customer Service at sales@seacomp.com or the sales contact you are working with.

Sincerely,
For and on behalf of SEACOMP



Cy Johnson
Director of Engineering

